Oil Field Environmental Incident Summary

Incident: 20141017102507 Date/Time of Notice: 10/17/2014 10:25 Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC. Well Name: REHAK FEDERAL 6-25H1 Field Name: ALKALI CREEK Well File #: 26273 Facility ID Number: MOUNTRAIL Twp: 155 **Rna**: 94 Sec: 25 Qtr: County: Location Description: Submitted By: Shane Knuchel Received By: Contact Person: Shane Knuchel PO BOX 268870 OKLAHOMA CITY, OK 73126 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Units Spilled Recovered Units Followup **Units** Oil **Brine** Other 2 Barrels **Barrels Description of Other Released Contaminant:** Crosslink gel Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None.

Areal Extent:

Potential Environmental Impacts:

None. Most contained on liner. Very little actually spread to well site soil.

Action Taken or Planned:

Gel was recovered from both liner and well site soil.

Wastes Disposal Location: All waste was recovered.

Agencies Involved: Bob Garby NDIC- notified by phone at 10:04 AM 10/17/2014

Updates

Date: 10/18/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak during fracking activities, remained on location according to the report. NDIC retains oversight.